

Abstract

A simulation method for three-dimensional processing by a CNC-controlled processing machine is determined by means of an initial data record which describes idealized processing instructions for a processing machine, wherein a control data record for a control unit controlling the processing machine is determined from the initial data record by means of an arithmetic unit. At least one two-dimensional projection of the processing is determined from the initial data record and/or the control data record and is displayed.